

CAUTION

- Ensure Sun Parallel Cable connection is made to the **Upper Port** on MPS III (see figure). Failure to comply with this caution may cause damage to printer.

